

FIM MotoGP™ Stewards Panel Activity Report - UPDATED

Rider:	#17 MUÑOZ	Issue:	Track Limits
Session:	Race		
Explanation	Exceeded track limits 5 times		
Action:	Issued a Long lap penalty - completed		

Rider:	#28 GUEVARA	Issue:	Technical Infringement – minimum weight
Session:	Race		
Explanation	Combined recorded weight of 215,8 kg which is below the required minimum combined weight of 217,0 kg		
Action:	Disqualification from the Race results		

MotoGP™

Rider:	#43 MILLER	Issue:	Crash with #10 #41 & #73 at turn 3
Session:	Race		
Explanation	After further review was determined to be a race incident		
Action:	No further action		

Rider:	#30 NAKAGAMI	Issue:	Technical Infringement - UPDATED
Session:	Race		
Explanation	Technical checks completed. Infraction confirmed.		
Action:	16 seconds time penalty applied after the race		

Rider:	#31 ACOSTA	Issue:	Technical Infringement
Session:	Race		
Explanation	The technical director advised during the race that the front tyre pressure of Acosta was under investigation. After completing the post-race technical checks, the pressure was correct at the beginning of the race and the loss of pressure during the race was proven to be due to leaking wheel rim. The Technical Director, together with the official tyre supplier determined that no infraction of the regulations occurred, according to Article 2.4.4.9.1 of the Technical regulations.		
Action:	No further action		

Rider:	#33 BINDER	Issue:	Technical Infringement - UPDATED
Session:	Race		
Explanation	Technical checks completed. No infraction found.		
Action:	No further action		

FIM MotoGP™ Stewards Panel